



TECNOpro “TL” Recalled Toe Component Identification Process

BEFORE REMOVING THE TOE COMPONENT FROM THE SKI:

Step 1: Check the TECNOpro binding for the “TL” brand, as indicated on this page.

TECNOpro TL



- Is the binding a  branded model TL 70, TL 80, TL 70 SP, TL 80 SP or TL 70 SR ?

YES – Then, please proceed to **Step 2**.

NO – The toe component of this binding is **NOT** subject to this recall.



Step 2: (If answered "YES" to **Step 1**) Inspect the toe component for a production date code found on the center plate where the toe of the ski boot contacts the toe component, as indicated in the following picture.



PRODUCTION DATE CODE LOCATION

Does the production date code end in the number "8" (for 2008)?

YES – The toe component of this binding **IS** subject to recall.

NO – This binding is **NOT** subject to the recall.

If the binding **IS** subject to the recall, then:

- **Consumers** should NOT DISASSEMBLE the bindings. Consumers should bring the bindings to an authorized Intersport Ski Dealer, and the authorized dealer will follow the recall procedures and replace the toe component of the binding.
- **Authorized Dealers** should follow the Dealer Guidelines.